GRAHAM + SIBBALD

Home Report

Mill of Kingcausie Newtonhill Stonehaven AB39 3PA

Date of Valuation: 10th October 2024 AIMS Ref: 2024/10/0037

single survey

survey report on:

Property address	Mill of Kingcausie Newtonhill Stongbayon
	Stonehaven AB39 3PA

Customer	Major Grenville Irvine-Fortescue	

Prepared by	Graham + Sibbald LLP
-------------	----------------------

1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	The subjects comprise a detached one storey and attic style cottage
	with single storey extension to the rear elevation.

Accommodation	GROUND FLOOR: Entrance Vestibule/Porch, Hallway, Living Room,
	Kitchen with Dining Room off, Bedroom, Bathroom.
	ATTIC FLOOR: Two Attic Rooms (accessed via steep staircase and there is limited headroom)
	The floor area noted below includes the attic rooms.

Gross internal floor area (m ²)	114 or thereby

Neighbourhood and location	The property is located within a rural setting, approximately 7 miles
	south of Aberdeen centre and accessed off the A92 dual carriageway.
	The subjects are a short distance from the commuter town of
	Portlethen where a range of facilities and amenities are available.

Age (year built)	Circa 1880
0 () /	

Weather	Dry and sunny.

Chimney stacks	The chimney stacks are of pointed stone construction.
	Visually inspected with the aid of binoculars where appropriate.

Roofing including roof space	 The main roof is of pitched timber frame design and clad with slates. The roof over the rear extension is of flat felt design. No access to any roof void areas was obtained, with any hatches identified screwed or painted shut at the time of inspection. Sloping roofs were visually inspected with the aid of binoculars where appropriate. Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder
	externally. Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property. If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.

Rainwater fittings	Rainwater fittings are generally formed in PVC.
	Visually inspected with the aid of binoculars where appropriate.

Main walls	The main walls are of traditional solid stone construction, rendered
	externally and painted. The walls of the rear extension appear to be
	of solid block/brick construction and are rendered externally.
	Visually inspected with the aid of binoculars where appropriate. Foundations and concealed parts were not exposed or inspected.

Windows, external doors and	The windows are predominantly PVC framed and double glazed with
joinery	there also being timber framed double glazed units and Velux style
	windows at attic level. The front entrance door is of timber
	construction. There are also patio doors off the dining area which are
	PVC framed and double glazed.
	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.

External decorations	Visually inspected.

Conservatories / porches	None.

Communal areas	None.

Garages and permanent	There is an attached outbuilding/workshop of stone construction
outbuildings	under a pitched roof, clad with profile metal sheeting. In addition,
	there is a traditional range of former steadings/outbuildings of stone
	construction with tiled roofs. These buildings are in a dilapidated state
	and internal access was not obtained. There are no further permanent
	outbuildings.
	Visually inspected.

Outside areas and boundaries	The house is set within garden grounds which are bounded by post
	and wire fencing or stone walls. Garden areas are part laid in grass
	and incorporate planted areas and mature shrubs and trees. Access
	to the property is via a driveway off the A92 dual carriageway.
	Visually inspected.

Ceilings	The ceilings are lined with lath and plaster or plasterboard.
	Visually inspected from floor level.

Internal walls	Internal walls appear to be lined with lath and plaster or plasterboard.
	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.

The main floors are part suspended timber and part solid concrete
design. First floor accommodation is of suspended timber
construction. A limited inverted head and shoulders inspection of the
sub-floor of the rear projection was carried out via a hatch in the
bathroom. A lack of clearance limited our inspection. No further
accessible hatches were identified within the limits of our inspection.
Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point.
Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so , and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.

Internal joinery and kitchen	The kitchen is fitted with limited range of units and worktops.
fittings	Internal doors, door surrounds and skirtings are of timber design.
	There is a timber staircase providing access to the attic
	accommodation.
	Built-in cupboards were looked into but no stored items were moved. Kitchen units were visually inspected excluding appliances.

Chimney breasts and fireplaces	There are chimney breast areas with there being a solid fuel stove
	fitted in the living room. There is also a feature fireplace in one of the
	attic rooms, however this does not appear to have been in use in
	recent years.
	Visually inspected. No testing of the flues or fittings was carried out.

Internal decorations	Visually inspected.

Cellars	None.

Electricity	Mains electricity is connected with the electrical apparatus located at the attic floor landing. There is a further unit in the attached workshop outbuilding.	
	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.	

Gas	No mains gas is connected.

1		
	Water, plumbing, bathroom fittings	Water is understood to be from the public supply. Plumbing, where visible, is formed in copper or PVC. No sight of the rising main was
		obtained.
		The bathroom is fitted with a bath, shower cubicle, wc and wash hand basin.
		Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the
		system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern
		standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
		It should be appreciated that concealed areas beneath and around
		baths and shower trays could not be inspected. Water spillage in these areas can result in dampness/decay and no comment can be
		made on inaccessible areas. Waterproof seals in sanitary areas should be checked and maintained on a regular basis.

Heating and hot water	There is an oil fired central heating system installed supplying
	radiators. The system is served by a Grant Vortex combination central
	heating and hot water boiler which is located in the attached
	outbuilding. The boiler is also understood to provide the domestic
	hot water.
	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. No tests whatsoever were carried out to the system or appliances.

Drainage	Drainage is understood to be to a private septic tank installation located to the south side of the house.
	Drainage covers etc were not lifted.
	Neither drains nor drainage systems were tested.

Fire, smoke and burglar alarms	New smoke alarm standards were introduced in Scotland in February
	2022 and it is likely that some properties may require additional
	works to meet these standards. In instances where alarms are in
	place, no tests whatsoever have been carried out and we cannot
	confirm if the system complies with the most recent regulations. Any
	potential purchaser should satisfy themselves as to whether the
	current system meets with regulations or otherwise.

Additional limits to increation	Fitted floor equatings in some rooms limited our inspection
Additional limits to inspection	Fitted floor coverings in some rooms limited our inspection.
	It is outwith the scope of this inspection to determine whether or not asbestos based products are present within the property. Asbestos was widely used in the building industry until around 1999, when it became a banned substance. If you have any concerns you should engage the services of a qualified asbestos surveyor.
	No inspection for Japanese Knotweed was carried out and unless otherwise stated for the purpose of this report, it is assumed that there is no Japanese Knotweed within the boundaries of the property or in neighbouring properties.
	It should be appreciated that the Home Report inspection is a nondisruptive visual inspection of the property as at the date of inspection and that we are unable to inspect parts of the property which are concealed or covered by floor coverings or contents in place at that time. Changing weather conditions can also affect aspects of the property which would not be apparent at the time of inspection.



Sectional Diagram showing elements of a typical house

1	Chimney pots
2	Coping stone
3	Chimney head
4	Flashing
5	Ridge ventilation
6	Ridge board
7	Slates/tiles
8	Valley guttering
9	Dormer projection
10	Dormer flashing
11	Dormer cheeks
12	Sarking
13	Roof felt
14	Trusses
15	Collar
16	Insulation
17	Parapet gutter
18	Eaves guttering
19	Rainwater downpipe
20	Verge boards / skews
21	Soffit boards
22	Partition wall
23	Lath / plaster
24	Chimney breast
25	Window pointing
26	Window sills
27	Rendering
28	Brickwork / pointing
29	Bay window
	projection
30	Lintels
31	Cavity walls / wall ties
32	Subfloor ventilator
33	Damp proof course
34	Base course
35	Foundations
36	Solum
37	Floor joists
38	Floorboards
39	Water tank
40	Hot water tank

Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

	Structural movement		
Repair		1	
Notes		There is evidence of settlement in the building but this is not inconsistent with a property of this age and type and on the basis of a single inspection appears to be longstanding.	
	Dampne	ess, rot and infestation	
Repair catego	ry	3	
Notes		Where tested with a moisture meter, high damp readings were identified at various areas of the property at floor, wall and ceiling level. There is evidence of rot and decay, for example, in the entrance porch and shower room. Evidence of woodworm was noted in the property. There is evidence of mice/vermin activity. It is recommended that a reputable timber/damp specialist firm be	
		employed to carry out a detailed inspection of the entire subjects and thereafter implement all necessary remedial works under cover of long term guarantee.	



Chimney stacks

Repair category	1	
Notes	These appeared generally in fair condition consistent with age. Age related weathering was noted. It should be appreciated that flashing details require on-going maintenance to ensure water tightness.	
Roofing	including roof space	
Repair category	2	
Notes	Several chipped or slipped slates were noted and there is weathering at ridge level and pointing. Weathering and moss was noted to the flat roof covering. We would point out flat roofs can be a troublesome feature with the material that covers them often have a limited lifespan. They require to be regularly checked and maintained. We were advised that roof repairs were carried out in November 2019. The roof coverings are of an age where ongoing and regular maintenance will be required and it would be prudent to seek the advice of a roofing contractor to comment on its current condition and expected lifespan. It should be noted no access to any roof void areas was obtained.	
Repair category	2	
Notes	It was noted that several downpipes discharge directly to the ground beneath. Rainwater fittings should be checked for adequacy during periods of heavy rainfall.	
Main wa	alls	
Repair category	2	

Notes	Main walls are in fair condition, with age related weathering evident. There is cracking to render and uneven areas. We understand that the house was re-whitewashed in May 2023.
Window	vs, external doors and joinery
Repair category	2
Notes	Maintenance repairs are required. In particular, a number of the double glazing seals are defective and have misted. Decay and rot was noted to sections of window units and joinery which will require repair and/or replacement in due course.
	Windows can be problematic and over time the operation of the windows can be affected and opening mechanisms damaged. It is therefore likely that maintenance/ repair will be required as part of an ongoing maintenance programme.
External	I decorations
Repair category	2
Notes	There is weathering to external decorations which require attention. It is important external decorations are well maintained in order to prolong lifespan.
Conserv	vatories / porches
Repair category	-
Notes	See relevant sections above.
Commu	nal areas
Repair category	N/A

Notes	
Garage	s and permanent outbuildings
Repair category	3
Notes	With regard to the attached store, some routine maintenance should be anticipated with weathering, localised decay and evidence of woodworm noted. Weathering was noted to timbers and walls. With regard to the former steading outbuildings and storage areas, these are in a dilapidated state and require significant maintenance overhaul/upgrading.
Outside	e areas and boundaries
Repair category	1
Notes	Outside areas have been adequately maintained. Boundaries would benefit from routine maintenance. Mature trees and shrubs should be cut back and maintained as necessary.
Ceilings	
Repair category	2
Notes	Uneven areas, cracks and wear was noted. Some decorative surfaces are finished with an Artex type product. Early forms of Artex may incorporate small amounts of asbestos based bonding materials and therefore specialist advice should be obtained prior to working on these areas to minimise the risk of releasing hazardous fibres.
Interna	l walls
Repair category	2

condition cons		Within the limits of our inspection these generally appeared in fair condition consistent with age. During redecoration some plaster filling/repair would be beneficial.
	Floors in	cluding sub-floors
Repair categor	Ϋ́	2
the shower cubicle where there is evidence of past leakage. Concealed a could not be inspected. Please see relevant section above regarding a fur recommended further inspection by a reputable firm of timber/damp		specialists. Some wear and uneven areas was noted to flooring commensurate
	Internal	joinery and kitchen fittings
Repair categor	ý	2
Notes		Wear and tear was noted to kitchen fittings and joinery. Internal glazing does not appear to be formed in safety glass. The property would benefit from a programme of modernisation and upgrading of fittings.
Ē	Chimney	y breasts and fireplaces
Repair categor	ТУ	1
Notes		All flue linings should be checked, repaired if necessary and swept prior to the fires being reused. It should be ensured that disused flues are capped and adequately vented.
	Internal	decorations
Repair categor	ý	2

I be property appears in tair decorative order although it is recognized that
The property appears in fair decorative order although it is recognised that on taking occupancy home owners may consider redecoration.
on taking occupancy nome owners may consider redecoration.
N/A
ty
2
Elements of the electrical installation are dated and would not comply with regulations, for example, there is an older fuse box and there are sockets through skirtings. As such we recommend that it be checked and upgraded as necessary by an NICEIC/SELECT registered Electrical Contractor. The Institution of Engineering and Technology recommends that inspections and testing are undertaken at least every ten years and on a change of occupancy. It should be appreciated that only the most recently constructed or re-wired properties will have installations which fully comply with IET regulations. The electrical installation was checked in 2020 and an Electrical Installation Condition Report prepared. Copies of the relevant documentation should be made available.
N/A
olumbing and bathroom fittings

Repair catego	ry	2
Notes		There is evidence of leakage at the shower cubicle with decay noted to skirtings and flooring adjacent. It is important sealants are well maintained in order to prevent leakage. Wear and tear was noted to fittings commensurate with age.
	Heating	and hot water
Repair catego	ry	1
Notes		No significant defects. It is assumed the central heating system has been installed and maintained to meet with regulations with particular regard to fluing and ventilation requirements. It is recommended to have heating and hot water systems tested immediately upon taking occupation and regularly thereafter.
	Drainag	e
Repair category		1
Notes		No significant defects evident with regard to our external inspection. It is assumed that the installation has been SEPA registered and complies with the relevant regulations.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	3
Chimney stacks	1
Roofing including roof space	2
Rainwater fittings	2
Main walls	2
Windows, external doors and joinery	2
External decorations	2
Conservatories / porches	-
Communal areas	-
Garages and permanent outbuildings	3
Outside areas and boundaries	1
Ceilings	2
Internal walls	2
Floors including sub-floors	2
Internal joinery and kitchen fittings	2
Chimney breasts and fireplaces	1
Internal decorations	2
Cellars	-
Electricity	2
Gas	-
Water, plumbing and bathroom fittings	2
Heating and hot water	1
Drainage	1

Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. Accessibility information

Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property: In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres: For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

 Which floor (s) is the living accommodation on? 		Groun	d Floor	
Are there three steps or fewer to a main entrance to a property?	Yes	Х	No	
 Is there a lift to the main entrance door of the property? 	Yes		No	Х
 Are all door openings greater than 750mm? 	Yes		No	Х
5. Is there a toilet on the same level as the living room and kitchen?	Yes	Х	No	
Is there a toilet on the same level as a bedroom?	Yes	Х	No	
7. Are all rooms on the same level with no internal steps or stairs?	Yes		No	Х
 Is there unrestricted parking within 2 metres of an entrance door to the building? 		Х	No	

4. Valuation and conveyance issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

Title Deeds should be consulted in order to confirm the boundaries of the property and with regard to any rights of way.

We assume that drainage is to a private septic tank installation. It should be confirmed that this is SEPA registered and complies with the relevant regulations.

We are unaware of any adverse planning proposals affecting the subjects although this should be confirmed by obtaining a Property Enquiry Certificate.

Absolute Ownership assumed. We are unaware of any easements, servitudes or rights of way which may adversely affect the property. This point should be confirmed by reference to the Title Deeds.

It is recommended that where repairs, defects or maintenance items have been identified interested parties make appropriate enquiries in order to satisfy themselves of potential costs and the extent of the works required prior to submitting a legal offer to purchase.

We are not aware of any structural alterations having been carried out to the property within the past 30 years.

Access to the attic floor accommodation is via a steep staircase which would not comply with regulations.

Estimated reinstatement cost for insurance purposes

£450,000

It is assumed that insurance cover is obtainable on normal terms. The guidance figure is the estimate of costs for reinstating the subjects as at the date of inspection based on information provided by the Building Cost Information Service (BCIS). It is recommended that this figure is kept under regular review to ensure that you have adequate insurance cover. We are of the opinion that the subjects should be insured for buildings reinstatement purposes for a sum of not less than £450,000 (Four Hundred and Fifty Thousand Pounds).

Valuation and market comments

£175,000

We are of the opinion that the market value of the subjects all as previously described and on a vacant possession basis would be fairly stated in the region of £175,000 (One Hundred and Seventy-Five Thousand Pounds Sterling).

Our valuation reflects current market conditions relating to this area. We would assume that current trends will prevail at the ultimate date of disposal with no adverse or onerous matters being introduced into the market during the intervening period which would have a detrimental effect on price.

	Report author	Eilidh Walker
--	---------------	---------------

Address	21 Carden Place, Aberdeen AB10 1UQ

Signed	EWolker
	Eilidh Walker For and on behalf of Graham + Sibbald LLP

Date of report	30/10/2024

TERMS AND CONDITIONS OF SINGLE SURVEY GENERAL

1.1 The Surveyors

The Seller has engaged the Surveyors to provide the Report and a Generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited energy company.

The Surveyors are authorised to provide a transcript or retype of the Generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by brokers and lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the Generic Mortgage Valuation Report. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the Generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and Generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors are required to amend the valuation in consequence of such information, they will issue an amended Report and Generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and Generic Mortgage Valuation Report to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon residential property. *

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's agent or relative to the Property, they will be obliged to indicate this in the adjacent box. ???

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

* Which shall be in accordance with the current RICS Appraisal and Valuation Standards (The Red Book) and RICS Rules of Conduct.

1.2 The Report

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to the 1st of December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Report is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Report may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective Purchasers and the Purchaser and their respective professional advisors without the prior written consent of the Surveyors.

1.3 Liability

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and is prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would be (or, as the case might be, would have been) disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisors of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

Graham + Sibbald's total liability to the Client (and any third party relying upon this report) under this Agreement (including liability in contract, tort (including negligence), breach of statutory duty, or otherwise) shall be limited to the lower of the following : a) 25% of the valuation or b) £250,000.

1.4 Generic Mortgage Valuation Report

The Surveyors undertake to the Seller that they will prepare a Generic Mortgage Valuation Report, which will be issued along with the Report. It is the responsibility of the Seller to ensure that the Generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 Transcript Mortgage Valuation for Lending Purposes

The Surveyors undertake that on being asked to do so by a prospective Purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. ** The Transcript Mortgage Valuation Report for Lending Purposes will be prepared from information contained in the Report and the Generic Mortgage Valuation Report.

** Which shall be in accordance with the current RICS Appraisal and Valuation Standards (The Red Book) and RICS Rules of Conduct.

1.6 Intellectual Property

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 Payment

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports, including replacement home reports.

1.8 Cancellation

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the Property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the Property, the Surveyor concludes that the Property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the following paragraph of this section.

In the case of cancellation by the Seller, for whatsoever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

If our account details change, we will notify these to you by letter or face to face and never by email.

1.9 Precedence

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.10 Definitions

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a Surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format.
- the "Market Value" is the estimated amount for which the Property should exchange, on the date of valuation, between a willing seller and a willing buyer in an arm's length transaction after proper marketing where the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in Part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property;
- the "Surveyors" are Graham + SIbbald LLP, a limited liability partnership incorporated in Scotland (Registered Number SO307130) and having its registered office address at Seabraes House, 18 Greenmarket, Dundee, DD1 4QB, of which the Surveyor is an employee, director or member (unless the Surveyor is not an employee, director or member, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report; and
- the "Energy Report" is the advice given by the accredited energy company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.
- "Data Protection Legislation" means the UK Data Protection Legislation and any other European Union legislation relating to personal data and all other legislation and regulatory requirements in force from time to time which apply to a party relating to the use of personal data (including, without limitation, the privacy of electronic communications).
- "UK Data Protection Legislation" means all applicable data protection and privacy legislation in force from time to time in the UK including the UK GDPR; the Data Protection Act 2018; the Privacy and Electronic Communications Directive 2002/58/EC (as updated by Directive 2009/136/EC) and the Privacy and Electronic Communications Regulations 2003 (SI 2003/2426) as amended.
- "UK GDPR" has the meaning given to it in section 3(10) (as supplemented by section 205(4)) of the Data Protection Act 2018.

DESCRIPTION OF THE REPORT

2.1 The Service

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by statute and this is in the format of the accredited energy company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 The Inspection

The inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the Property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the Property.

The inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the Report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Report of Property that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a register of asbestos and effective management plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 The Report

The Report will be prepared by the Surveyor who carried out the Property inspection and will describe various aspects of the Property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the Property will be concise and will be restricted to matters that could have a material affect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the Property is free of any other minor defects.

Throughout the Report the following repair categories will be used to give an overall opinion of the state of repair and condition of the Property:

2.3.1 Category 3:

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the Property or cause a safety hazard. Estimates for repairs or replacement are needed now.

2.3.2 Category 2:

Repairs or replacement requiring future attention, but estimates are still advised.

2.3.3 Category 1:

No immediate action or repair is needed.

WARNING:

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the Property. This is particularly true during slow market conditions when the effect can be considerable. Parts of the Property which cannot be seen or accessed will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 Services

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 Accessibility

A section is included to help identify the basic information interested parties need to know to decide whether to view a Property.

2.6 Energy Report

A section is included that makes provision for an Energy Report, relative to the Property. The Surveyor will collect physical data from the Property and provide such data in a format required by an accredited Eeergy company. The Surveyor cannot of course accept liability for any advice given by the energy company.

2.7 Valuation & Conveyancer Issues

The last section of the Report contains matters considered relevant to the conveyancer (solicitor). It also contains the Surveyor's opinion both of the market value of the Property and of the re-instatement cost, as defined below.

"Market Value" is the estimated amount for which a property should exchange on the date of valuation within a willing buyer and willing seller in an armslength transaction after proper marketing wherein the parties have each acted knowledgably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of uninspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions.

• There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a re-inspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

It is assumed that any relevant Local Authority consents, warrants and completion certificates have been obtained where construction or alteration works have been undertaken.

This agreement and any dispute or claim arising out of or in connection with its subject matter shall be governed by and construed in accordance with the laws of Scotland, and the Scottish Courts will have exclusive jurisdiction to hear such claims.

DATA PROTECTION

Graham + Sibbald and the Client each undertake that:

- (a) they shall comply with all applicable requirements of the Data Protection Legislation, including without limitation any obligations relating to the rights of a data subject and the reporting of personal data breaches (all as defined in the UK GDPR); and
- (b) not do or omit to do anything which puts any other party to the Agreement in breach of the Data Protection Legislation.

Without prejudice to the generality of this clause, you shall ensure that you have all necessary appropriate consents and notices in place to enable lawful transfer of the personal data to Graham + Sibbald for the duration and purposes of this Agreement. You shall have liability for and shall indemnify Graham + Sibbald for any loss, liability, costs (including legal costs), damages, or expenses resulting from any breach by you of the Data Protection Legislation. For further information regarding how Graham + Sibbald processes personal data in relation to this Agreement, please see Graham + Sibbald's privacy notice on their website.

M	ortgage Valuation Repo	ort for Home Repo	ort	GR SIB	AHAM BALD
Source: G+S Home Report	Seller Name	1ajor Grenville Irvine	e-Fortesque	Reference ABD	-2024\10\0037
	se Name Mill of Kingcausie ber / Ext Street Area Newtonhill Town Stonehaven	Postcode AB3	9 3PA		
2) Description of property Property Type Hous Year Built Circa 1880	Non Tradition	Detached al Construction? No ler general comments)		r of subject pro No. of floors in No. of flats	block
3) Accommodation - give numb Receptions 2 Bedroon		Bathrooms 1	Total Inside W.	.C.S. 1 No	of floors 2
Other 2 attic rooms	Garage(s) Parking Space	Outbuildings 2		Garden Yes	
4) Tenure Absolute Ownership Any known or reported probler		d, years unexpired:	harges?		
No					
Owner occupied Tena	nted Vacant _X				
If part tenanted, please give details					
5) Subsidence, Settlement and Does the property show signs subject to landslip, heave, se If yes, please clarify	of, or is the property located				
6) Condition of Property					
	ntial internal repairs required	1?		Yes	X No
	ntial external repairs required			Yes	No x
	cted before the advance is r mortgage retention recomn			Yes Yes	No x No x
If the answer to any of the abo				Tes	NO X
, Dampness and decay are evid employed to carry out a detai under cover of long term guar with regard to the further ins	ent in the property. It is rec led inspection of the entire antee. No retention is cons	commended that a re subjects and thereaft	er implement a	III necessary re	medial works
		Page 1 of 3			Regulated by RICS Chartered Surveyors A Quality Assured Firm

7) Services Mains water x Mains drainage x Electricity x Gas Central heatin	g Oil		
8) Insurance Reinstatement Value	114 or thoroby		
Total area of all floors measured internally (m ²) Cost of rebuilding inc. demolition, site clearance, professional fees, local authority requirements	114 or thereby		
and main building (inc all other structures within the site boundaries unless specifically exclude			
9) Market Valuation for Mortgage Purposes (Assuming Vacant Possession) Comment on mortgageability			
In our opinion the property forms suitable security for loan purposes subject to specific lendr's cri	iteria which may vary.		
Valuation in present condition:	£175,000		
Valuation on completion of any works required under Question 6:			
10) General Comments Please advise of any special features of the property and/or the location, which affects the property is located within a rural setting, approximately 7 miles south of Aberdeen off the A92 dual carriageway. The subjects are a short distance from the commuter to the property is located within a rural setting are a short distance from the commuter to be a subject of the advised of the advised of the property is located within a rural setting.	city centre and accessed		
range of facilities and amenities are available. Title Deeds should be consulted in order to confirm the boundaries of the property and of way.	d with regard to any rights		
We are unaware of any adverse planning proposals affecting the subjects although this obtaining a Property Enquiry Certificate.	s should be confirmed by		
Absolute Ownership assumed. We are unaware of any easements, servitudes or rights of way which may adversely affect the property. This point should be confirmed by reference to the Title Deeds.			
It is recommended that where repairs, defects or maintenance items have been identif make appropriate enquiries in order to satisfy themselves of potential costs and the ex required prior to submitting a legal offer to purchase.			
At the time of inspection the property was in reasonable condition, however there are required.	maintenance repairs		
Access to the attic floor accommodation is via a steep staircase which would not comp	ly with regulations.		
IMPORTANT - THIS IS A CONFIDENTIAL REPORT PREPARED FOR MORTGAGE PURPOSES. Certificate: I have personally inspected the property described herein and confirm adequate protheld.	fessional indemnity cover is		
Company / Firm Name C	Graham + Sibbald LLP		
Children Office Name			
	21 Carden Place		
Office Addr2			
Valuer name and Eilidh Walker MRICS Area qualification For and on behalf of Graham + Sibbald LLP			
Date of inspection 10/10/2024	Aberdeen		
Date of report 30/10/2024	AB10 1UQ		
	01224 625024		
Page 2 of 3			

MORTGAGE VALUATION TERMS AND CONDITIONS

In these Terms and Conditions of Engagement, the following expressions shall have the following meanings:

"Agreement" means these Terms and Conditions of Engagement, the Instructions and the confirmation letter issued by Graham + Sibbald. "Client"/"you"/"your" means the person, firm, company, organisation or other entity engaging Graham + Sibbald to provide the inspection services. "Data Protection Legislation" means the UK Data Protection Legislation and any other European Union legislation relating to personal data and all other legislation and regulatory requirements in force from time to time which apply to a party relating to the use of personal data (including, without limitation, the privacy of electronic communications).

"Graham + Sibbald"/"we"/"us"/"our" means Graham + Sibbald, a limited liability partnership incorporated in Scotland (Registered Number SO30713) and having its registered office address at Seabraes House, 18 Greenmarket, Dundee, DD1 4QB

"Instructions" means the written or verbal instructions by the Client to Graham + Sibbald, which appoint Graham + Sibbald to provide the inspection services.

"Property" means the property identified and described in the Instructions. "UK Data Protection Legislation" means all applicable data protection and privacy legislation in force from time to time in the UK including the UK GDPR; the Data Protection Act 2018; the Privacy and Electronic Communications Directive 2002/58/EC (as updated by Directive 2009/136/EC) and the Privacy and Electronic Communications Regulations 2003 (SI 2003/2426) as amended.

"UK GDPR" has the meaning given to it in section 3(10) (as supplemented by section 205(4)) of the Data Protection Act 2018.

A valuation for mortgage is a limited inspection and report produced for building societies, banks and other lenders to enable them to make a lending decision. IT IS NOT A SURVEY. Unless otherwise stated the date of valuation will be the date of inspection.

This report is used to guide the lender on the market value of the Property for mortgage purposes and is carried out for this purpose alone. Although the inspection will be carried out by a valuer who will usually be a gualified surveyor it is not a detailed inspection of the Property, and only major visible defects will be noted. Subject to reasonable accessibility, the roof space is inspected only to the extent visible from the access hatch without entering it. The surveyor will not inspect under floor areas, communal roof space or other parts not readily accessible. The exterior and roof of the Property will be inspected from ground level only from within the boundaries of the site and adjacent/communal public areas. The area of the Property will be taken into account, and the rooms individually inspected, but floor coverings and furniture will not be moved. Services (such as water, gas, electricity and drainage) will not be tested and we will not advise as to whether these comply with regulations in respect of these services. The surveyor may recommend that a part of the mortgage be retained by the lenders until such time as particular repair works are carried out. Similarly, the report may suggest that the borrower should undertake to carry out certain repairs or commission more extensive investigation where hidden defects are suspected since these may have a material effect on the value of the Property. If a retention is recommended then the figure should not be regarded as an estimate of repair costs. Its purpose is to protect the interests of the lending institution. It is recommended that detailed estimates be obtained before proceeding with the purchase. Attention is drawn to the fact that if a subsequent transcription of this report is prepared on a lenders form, then in order to comply with the lenders specific requirements, the wording or phraseology may differ. Many people rely on the mortgage valuation certificate in the mistaken belief that it is a detailed survey. The report is often made available to house buyers by lenders, but this does not mean that it should be relied upon as a report on the condition of the building.

The definition of 'market value' is the estimated amount for which a Property should exchange on the date of valuation, between a willing buyer and a willing seller in an arms-length transaction after proper marketing wherein the parties had acted knowledgeably, prudently and without compulsion. For the purpose of this market value the surveyor has assumed that vacant possession will be provided. Unless otherwise stated the surveyor has valued the interest on a comparable basis.

The inspection that has been undertaken should not be regarded as a survey. The surveyor did not inspect parts of the Property which were covered, unexposed or inaccessible and are therefore unable to report that any such part of the Property is free from defect. Defects which are not considered materially to affect the value of the Property or other matters which would be attended to during maintenance, may not have been mentioned. If defects have been mentioned in this report, they should be regarded as indicative and not exhaustive. For the purposes of this valuation

the surveyor assumes that all uninspected areas are free from defect which would have a material effect on value.

In accordance with our normal practice, we must state that this report is for the use only of the party to whom it is addressed or their named client and no responsibility is accepted to any third party for the whole or any part of its content. In addition, we would bring to your attention that neither the whole nor any part of this report, nor any reference thereto, may be included in any document, circular or statement without prior written approval of the form and context in which it will appear.

The surveyor shall, unless otherwise expressly agreed, rely upon information provided by the Client and/or the Client's legal or other professional advisers relating to tenure, leases and all other relevant matters. For the purposes of this valuation the surveyor has assumed that all ground burdens are nominal or have been redeemed and that there are no unusual outgoings or onerous restrictions contained within the titles of which we have no knowledge. The surveyor has further assumed that the subjects are

unaffected by any adverse planning proposals. Unless otherwise stated, it is assumed that all the required valid planning permissions and statutory approvals for the building and for their use, including any recent or significant extensions or alterations, have been obtained and complied with. It has been further assumed that no deleterious or hazardous materials or techniques have been used in the construction of the subject and that there is no contamination in or from the ground or from the immediate surrounds.

The surveyor will not carry out an asbestos inspection and will not be acting as an asbestos inspector in completing a valuation inspection of Property that may fall within the Control of Asbestos Regulations 2012. No enquiry of the duty holder, as defined in the Control of Asbestos Regulations 2012, of the existence of an asbestos register, or of any plan for the management of asbestos will be made. Your legal adviser/conveyancer should confirm the duty holder under these regulations, the availability of an asbestos register and the existence and management of any asbestos containing materials. For the purposes of this valuation, the surveyor has assumed that there is a duty holder, as defined in the Control of Asbestos Regulations 2006, and that a register of asbestos and effective management plan is in place which does not require any immediate expenditure or pose a significant risk to health or breach the HSE Regulations.

The surveyor confirms that this mortgage valuation is prepared in accordance with the RICS Valuation - Global Standards 2017 and incorporating IVSC International Valuation Standards and, unless other stated, we are External Valuers as defined therein. Further information may also be obtained from the Royal Institution of Chartered Surveyors in Scotland, 10 Charlotte Square, Edinburgh, EH2 4DR. Tel no 0131 225 7078. As part of this remit, the surveyor may, where he/she feels qualified and experienced to do so, provide general comment on standard appropriate supplementary documentation, presented to us by the Client's lender and conveyancer. In the event of a significant amount of documentation being provided to us, an additional fee may be incurred. Any additional fees will be agreed with you in advance.

We confirm that Graham + Sibbald operates formal procedures to deal with complaints from clients in accordance with By-law 19, Regulation 2.7 of the Royal Institution of Chartered Surveyors Rules of Conduct and Disciplinary Procedures. A copy of this procedure is available on request. Graham + Sibbald's total liability to the Client (and any third party relying upon this report) under this Agreement (including liability in contract, tort (including negligence), breach of statutory duty, or otherwise) shall be limited to the lower of the following: a) 25% of the valuation or b) £250,000. This agreement and any dispute or claim arising out of or in connection with its subject matter shall be governed by and construed in accordance with the laws of Scotland, and the Scottish courts will have exclusive jurisdiction to hear such claims.

Graham + Sibbald and the Client each undertake that:

- (a) they shall comply with all applicable requirements of the Data Protection Legislation, including without limitation any obligations relating to the rights of a data subject and the reporting of personal data breaches (all as defined in the UK GDPR); and
- (b) not do or omit to do anything which puts any other party to the Agreement in breach of the Data Protection Legislation.

Without prejudice to the generality of this clause, you shall ensure that you have all necessary appropriate consents and notices in place to enable lawful transfer of the personal data to Graham + Sibbald for the duration and purposes of this Agreement. You shall have liability for and shall indemnify Graham + Sibbald for any loss, liability, costs (including legal costs), damages, or expenses resulting from any breach by you of the Data Protection Legislation. For further information regarding how Graham + Sibbald processes personal data in relation to this Agreement, please see Graham + Sibbald's privacy notice at https://www.g-s.co.uk/privacy-policy/.

Energy Performance Certificate (EPC)

Scotland

Dwellings

MILL OF KINGCAUSIE, NEWTONHILL, STONEHAVEN, AB39 3PA

Dwelling type:	Detached house
Date of assessment:	11 October 2024
Date of certificate:	17 October 2024
Total floor area:	114 m ²
Primary Energy Indicator:	392 kWh/m²/year


Reference number: Type of assessment: Approved Organisation: Main heating and fuel: 9014-8520-4009-0889-5296 RdSAP, existing dwelling Elmhurst Boiler and radiators, oil

You can use this document to:

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your home for 3 years*	£8,565	See your recommendations
Over 3 years you could save*	£4,353	report for more information

based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions



Very environmentally friendly - lower CO₂ emissions (92 plus) B (81-91) 83 (69-80) (55-68) D (39-54 (21-38) F 28(1-20) G Not environmentally friendly - higher CO₂ emissions

Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band F (33)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band F (28)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 Flat roof or sloping ceiling insulation	£850 - £1,500	£282.00
2 Room-in-roof insulation	£1,500 - £2,700	£2133.00
3 Internal or external wall insulation	£4,000 - £14,000	£1107.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282. THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

MILL OF KINGCAUSIE, NEWTONHILL, STONEHAVEN, AB39 3PA 17 October 2024 RRN: 9014-8520-4009-0889-5296

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Granite or whinstone, as built, no insulation (assumed)	★★☆☆☆	*****
	Solid brick, as built, no insulation (assumed)	$\bigstar\bigstar \bigstar \clubsuit \checkmark \checkmark \checkmark \checkmark$	$\bigstar\bigstar \bigstar \clubsuit \clubsuit \clubsuit \clubsuit$
Roof	Pitched, no insulation (assumed)	****	****
	Flat, limited insulation (assumed)	*****	$\bigstar \mathring{a} \Leftrightarrow \mathring{a} \Leftrightarrow \mathring{a}$
	Roof room(s), no insulation (assumed)	$\bigstar \pounds \pounds \pounds \pounds \pounds$	$\bigstar \mathring{\Delta} \stackrel{\bullet}{\Delta} \stackrel{\bullet}{$
Floor	Solid, no insulation (assumed)	_	_
	Suspended, no insulation (assumed)	—	—
Windows	Fully double glazed	★★★ ☆☆	★★★☆☆
Main heating	Boiler and radiators, oil	★★★☆☆	★★★☆
Main heating controls	Programmer, TRVs and bypass	★★★☆☆	****
Secondary heating	Room heaters, dual fuel (mineral and wood)	—	_
Hot water	From main system	★★★ ☆☆	★★★☆☆
Lighting	Low energy lighting in 83% of fixed outlets	****	****

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 102 kg $CO_2/m^2/yr$.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 12 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 9.2 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

Estimated energy costs for this home			
	Current energy costs	Potential energy costs	Potential future savings
Heating	£7,395 over 3 years	£3,198 over 3 years	
Hot water	£780 over 3 years	£624 over 3 years	You could
Lighting	£390 over 3 years	£390 over 3 years	save £4,353
Total	s £8,565	£4,212	over 3 years

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Recommended measures		Indicative cost	Typical saving	Rating after improvement	
		indicative cost	per year	Energy	Environment
1	Flat roof or sloping ceiling insulation	£850 - £1,500	£94	F 34	F 30
2	Room-in-roof insulation	£1,500 - £2,700	£711	E 50	E 43
3	Internal or external wall insulation	£4,000 - £14,000	£369	D 60	E 51
4	Floor insulation (suspended floor)	£800 - £1,200	£52	D 61	E 53
5	Floor insulation (solid floor)	£4,000 - £6,000	£106	D 64	D 56
6	Upgrade heating controls	£350 - £450	£65	D 65	D 58
7	Solar water heating	£4,000 - £6,000	£54	D 67	D 60
8	Solar photovoltaic panels, 2.5 kWp	£3,500 - £5,500	£428	C 76	D 68
9	Wind turbine	£15,000 - £25,000	£1025	A 93	B 83

Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.

energ

About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Flat roof or sloping ceiling insulation

Insulating a flat roof or sloping ceiling will significantly reduce heat loss through the roof; this will improve levels of comfort, reduce energy use and lower fuel bills. Insulation can be placed on top of the roof under the waterproof membrane and should particularly be considered when the waterproofing needs to be replaced. Further information about roof insulation and details of local contractors can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk). Building regulations generally apply to this work so it is best to check with your local authority building standards department.

2 Room-in-roof insulation

Insulating roof rooms will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. If it has a flat ceiling insulation can usually be added above the ceiling, and sloping ceilings and walls of roof rooms can be insulated using an internal lining board. Roof voids must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about roof room insulation and details of local contractors can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk). Building regulations generally apply to this work so it is best to check this with your local authority building standards department.

3 Internal or external wall insulation

Internal or external wall insulation involves adding a layer of insulation to either the inside or the outside surface of the external walls, which reduces heat loss and lowers fuel bills. As it is more expensive than cavity wall insulation it is only recommended for walls without a cavity, or where for technical reasons a cavity cannot be filled. Internal insulation, known as dry-lining, is where a layer of insulation is fixed to the inside surface of external walls; this type of insulation is best applied when rooms require redecorating. External solid wall insulation is the application of an insulant and a weather-protective finish to the outside of the wall. This may improve the look of the home, particularly where existing brickwork or rendering is poor, and will provide longlasting weather protection. Further information can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk). It should be noted that a building warrant is required for the installation of external wall insulation. Planning permission may also be required and that building regulations apply to external insulation so it is best to check with your local authority on both issues.

4 Floor insulation (suspended floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Suspended floors can often be insulated from below but must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work so it is best to check with your local authority building standards department.

5 Floor insulation (solid floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Insulating solid floors can present challenges; insulation laid on top of existing solid floors may impact on existing doors and finishes whilst lifting of a solid floor to insert insulation below will require consideration of the potential effect on both structural stability and damp proofing. It is advised to seek advice from a Chartered Structural Engineer or a registered Architect about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work and may also require a building warrant so it is best to check with your local authority building standards department.

6 Heating controls (room thermostat)

The heating system should have a room thermostat to enable the boiler to switch off when no heat is required. A competent heating engineer should be asked to do this work. Insist that the thermostat switches off the boiler as well as the pump and that the thermostatic radiator valve is removed from any radiator in the same room as the thermostat. Building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority building standards department and seek advice from a qualified heating engineer.

7 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

8 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

9 Wind turbine

A wind turbine provides electricity from wind energy. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Wind turbines are not suitable for all properties. The system's effectiveness depends on local wind speeds and the presence of nearby obstructions, and a site survey should be undertaken by an accredited installer. Planning permission might be required and building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for a wind turbine, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	28,761	(1,796)	N/A	(4,084)
Water heating (kWh per year)	3,446			

Addendum

This dwelling has stone walls and so requires further investigation to establish whether these walls are of cavity construction and to determine which type of wall insulation is best suited.

MILL OF KINGCAUSIE, NEWTONHILL, STONEHAVEN, AB39 3PA 17 October 2024 RRN: 9014-8520-4009-0889-5296

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name:	Miss Eilidh Walker
Assessor membership number: Company name/trading name:	EES/008996 Graham & Sibbald
Address:	21 Carden Place
Address.	Aberdeen
	AB10 1UQ
Phone number:	01224 625024
Email address:	aberdeen@g-s.co.uk
Related party disclosure:	No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.





Property address	Mill of Kingcausie
	Newtonhill
	Stonehaven
	AB39 3PA

Seller(s)	Mr Grenville I rvine-Fortescue
-----------	--------------------------------

Completion date of property questionnaire	08/10/2024
---	------------

GRAHAM - SIBBALD

Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

Information to be given to prospective buyer(s)

1.	Length of ownership		
	How long have you owned the property? Since 1968		
2.	Council tax		
	Which Council Tax band is your property in? C		
3.	Parking		
	What are the arrangements for parking at your property? (Please tick all that apply) • Garage • Allocated parking space • Driveway • Shared parking • On street • Resident permit • Metered parking • Other (please specify):	driveway leading from	
4.	Conservation area		
	Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?	Νο	

5.	Listed buildings		
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?	Νο	
6.	Alterations/ additions/ extensions		
a.	(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	Yes	
	If you have answered yes, please describe below the changes which you have made:		
	A considerable number of years ago, an extension was added to the rear of the property.		
	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?		
	If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.		
	If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:		
b.	Have you had replacement windows, doors, patio doors or double glazing installed in your property?	Yes	
	<u>If you have answered yes</u> , please answer the three questions below:		
	(i) Were the replacements the same shape and type as the ones you replaced?	Yes	
	(ii) Did this work involve any changes to the window or door openings?	Νο	
	(iii) Please describe the changes made to the windows dates when the work was completed):	doors, or patio doors (with approximate	
	The changes were made a considerable number o details.	f years ago and I do not have the	
	Please give any guarantees which you received for this	work to your solicitor or estate agent.	

7.	Central heating	
a.	Is there a central heating system in your property?	
	(Note: a partial central heating system is one which does not heat all the main rooms of the property —	Yes
	the main living room, the bedroom(s), the hall and the bathroom).	
	<u>If you have answered yes or partial</u> – what kind of central heating is there?	
	(Examples: gas-fired, solid fuel, electric storage heating, gas warm air).	
	Oil fired	
	<u>If you have answered yes</u> , please answer the three questions below:	
	 (i) When was your central heating system or partial cent N/ K 	ral heating system installed?
	(ii) Do you have a maintenance contract for the central No heating system?	
	If you have answered yes, please give details of the company with which you have a maintenance contract:	
	(iii) When was your maintenance agreement last renewed year).	I? (Please provide the month and
8.	Energy Performance Certificate	
	Does your property have an Energy Performance Certificate which is less than 10 years old?	Yes
9.	Issues that may have affected your property	
a.	Has there been any storm, flood, fire or other structural damage to your property while you have owned it?	Νο
	If you have answered yes, is the damage the subject of any outstanding insurance claim?	
b.	Are you aware of the existence of asbestos in your property?	Νο
	If you have answered yes, please give details:	
	Note- EI CR Testing was carried out in 2020.	

10.

Services

a. Please tick which services are connected to your property and give details of the supplier:

Servio	ces	Connected	Suppl	ier
Gas or liquid petrole gas				
Water mains private water supply	or Ə	Yes	Mains	
Electri	city	Yes	Scotti	sh Gas
Mains draina	ge			
Teleph	none			
Cable or sate				
Broadl	band			
	1			1
	Isth	nere a septic tank system at your property?		Yes
		o <u>u have answered yes</u> , please answer th questions below:	е	
	(iv) discl	Do you have appropriate consents fo narge from your septic tank?	or the	Νο
	(v) your	Do you have a maintenance contract septic tank?	for	Νο

If you have answered yes, please give details of

the company with which you have a

maintenance contract:

11.	Responsibilities for shared or common areas		
a.	Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area?	Νο	
	If you have answered yes, please give details:		
b.	Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?	Not Applicable	
	<u>If you have answered yes</u> , please give details:		
с.	Has there been any major repair or replacement of any part of the roof during the time you have owned the property?	Νο	
d.	Do you have the right to walk over any of your neighbours' property — for example to put out your rubbish bin or to maintain your boundaries?	Νο	
	If you have answered yes, please give details:		
	Not applicable		
e.	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?	Νο	
	<u>If you have answered yes</u> , please give details: Not applicable		
f.	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately-owned.)	Νο	
	If you have answered yes, please give details:		
12.	Charges associated with your property		
a.	Is there a factor or property manager for your property?	Yes	
	If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:		
	I as the Landlord is the manager of the property		

b.	Is there a common buildings insurance policy?	Yes
	If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges?	Νο
c.	Please give details of any other charges you have to of common areas or repair works, for example to a or stair fund.	
	No charges.	
13.	Specialist works	
a.	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?	Yes
	If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.	
	In 2019 repair work was carried out on a leak in the roof and re plastering work was also carried out.	
b.	As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?	
	If you have answered yes, please give details:	
с.	If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work?	Νο
	If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself <u>please write</u> <u>below who has these documents</u> and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate.	
	Guarantees are held by:	

Are there any guarantees or warranties for	or any of the following:		
	Are there any guarantees or warranties for any of the following:		
Electrical work	Νο		
Roofing	Νο		
Central heating	Νο		
National House Building Council (NHBC)	Νο		
Damp course	Νο		
Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)	No		
If you have answered 'yes' or 'with title d to which the guarantee(s) relate(s):	eeds', please give details of the work or	installations	
c. Are there any outstanding claims under any of the guarantees listed above?		0	
<u>If you have answered yes</u> , please give de	ails:		
Boundaries			
So far as you are aware, has any bounda moved in the last 10 years?	y of your property been N	0	
If you have answered yes, please give de	tails:		
	Roofing Central heating National House Building Council (NHBC) Damp course Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy) If you have answered 'yes' or 'with title do to which the guarantee(s) relate(s): Are there any outstanding claims under an listed above? If you have answered yes, please give def Boundaries So far as you are aware, has any boundar moved in the last 10 years?	Roofing No Central heating No National House Building Council (NHBC) No Damp course No Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy) No If you have answered 'yes' or 'with title deeds', please give details of the work or to which the guarantee(s) relate(s): N Are there any outstanding claims under any of the guarantees listed above? N If you have answered yes, please give details: N Boundaries N So far as you are aware, has any boundary of your property been N	

16.	Notices that affect your property			
	In the past three years have you ever received a notice:			
a.	advising that the owner of a neighbouring property has made a planning application?	Νο		
b.	that affects your property in some other way?	Νο		
с.	that requires you to do any maintenance, repairs or improvements to your property?	Νο		
	If you have answered yes to any of a-c above, please g estate agent, including any notices which arrive at any purchaser of your property.			

Declaration by the seller(s)/ or other authorised body or person(s)

I/We confirm that the information in this form is true and correct to the best of $my/our\ knowledge$ and belief.

і ассерт 🗹

Name: Major Grenville Irvine-Fortescue

Date: 08/10/2024