YOUR ONESURVEY HOME REPORT

ADDRESS

Milton House 54 Main Street Milton of Balgonie, Glenrothes KY7 6PX

INSPECTION CARRIED OUT BY:

PREPARED FOR

Harry Aitchison

SELLING AGENT:

Galbraith

HOME REPORT GENERATED BY:





Document Index

Document	Status	Prepared By	Prepared On
Single Survey	Final	Dunfermline - Allied Surveyors Scotland Ltd	20/09/2024
Mortgage Certificate	Final	Dunfermline - Allied Surveyors Scotland Ltd	20/09/2024
Property Questionnaire	Final	Mr. Harry Aitchison	19/09/2024
EPC	Final	Dunfermline - Allied Surveyors Scotland Ltd	11/10/2024

Important Notice:

This report has been prepared for the purposes and use of the person named on the report. In order to ensure that you have sight of a current and up to date copy of the Home Report it is **essential** that you log onto www.onesurvey.org (free of charge) to download a copy personalised in your own name. This enables both Onesurvey and the Surveyor to verify that you have indeed had sight of the appropriate copy of the Home Report prior to your purchasing decision. This personalised report can then be presented to your legal and financial advisers to aid in the completion of your transaction. **Failure to obtain a personalised copy may prevent the surveyor having any legal liability to you as they will be unable to determine that you have relied on this report prior to making an offer to purchase.**

Neither the whole, nor any part of this report may be included in any published document, circular or statement, nor published in any way without the consent of Onesurvey Ltd. Only the appointed Chartered Surveyor can utilise the information contained herein for the purposes of providing a transcription report for mortgage/loan purposes.



SINGLE Survey

A report on the condition of the property, with categories being rated from 1 to 3.



Single Survey

Survey report on:

Surveyor Reference	DD1277
Customer	Mr. Harry Aitchison
Selling address	Milton House 54 Main Street
	Milton of Balgonie, Glenrothes
	KY7 6PX

Date of Inspection	20/09/2024
--------------------	------------

Prepared by	Peter Bennet, MRICS
	Dunfermline - Allied Surveyors Scotland Ltd

PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property. ¹

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

 $\overline{\mathcal{M}}$

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

¹ Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Codes of Conduct

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report. 2

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for

expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.10 **DEFINITIONS**

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format.
- the "Market Value" is The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property.
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and

² Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Rules of Conduct.

- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 – DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, *visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.*

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not

significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 2.3.1 <u>Category 3</u>: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2.3.2 <u>Category 2</u>: Repairs or replacement requiring future attention, but estimates are still advised.
- 2.3.3 <u>Category 1</u>: No immediate action or repair is needed.

WARNING: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- *There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- *There are no particularly troublesome or unusual legal restrictions;
- *There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" *is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form* unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property

1. INFORMATION AND SCOPE OF INSPECTION

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the Surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the Surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the Surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities will not be inspected or reported on.

Description	The subjects comprise a large Georgian detached villa with rear/side extensions.
Accommodation	GROUND FLOOR:
	Entrance Vestibule/Hall, Living Room, Dining Room, Large Open Plan Orangery/further Living Space to the rear, Dining Kitchen, Shower Room and Utility Room.
	FIRST FLOOR:
	Landing, Further Living Room, Two Bedrooms and Shower Room.
	ATTIC FLOOR:
	Two further Bedrooms and Bathroom.
Gross internal floor area (m2)	280 m2 (approx)
Neighbourhood and location	The subjects are situated close to the centre of the village of Milton of Balgonie within an established residential location, where surrounding properties are of a residential nature. All normal local amenities and facilities are available locally and within the nearby town of Glenrothes, which lies approximately 2 miles to the West.
Age	1795 (approx). The subjects were substantially extended to the rear circa 10 years ago.
Weather	Dry but overcast.
Chimney stacks	Original solid stone chimney stacks are provided, which incorporate clay pots and are protected by coping stones.
	Visually inspected with the aid of binoculars where required.

The roofing structure is of a timber pitched design, slate clad externally, and incorporates some metal flashings. Furthermore, a Velux window is situated to the rear elevation.
The rear extension/Orangery incorporates a significant pitched pergola style roof covering with glass sections throughout. These are understood to be self-cleaning, and are supported with metal collars etc.
Solar panels are fitted onto flat areas on the rear.
Access to the roof void area is minimal within areas, as the attic incorporates living accommodation.
Sloping roofs were visually inspected with the aid of binoculars where required.
Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder externally. Flat roofs have a limited life and depending on their age and quality of workmanship can fail at any time.
Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property. If this is not possible, then physic
Cast iron gutters/downpipes are provided. The front elevation incorporates some stone Ogee sections.
Visually inspected with the aid of binoculars where required.
The main walls of the building are of traditional solid stone construction (approximately 700mm thick).
The rear extension/Orangery again, is in reclaimed stone materials.
Visually inspected with the aid of binoculars where required. Foundations and concealed parts were not exposed or inspected.
Windows are in timber/timber double glazed sash and case materials. External doors are in timber materials.
Internal and external doors were opened and closed where keys were available.
Random windows were opened and closed where possible.
Doors and windows were not forced open.
Decorated areas include timber work and masonry.
Visually inspected.
None provided.
None provided.

Garages and permanent outbuildings	A large double attached car garage is situated to the rear/side of the property. This is constructed of brick materials with a smooth render finish, under a timber pitched/hipped roof, slate clad externally. The garage has timber shutter doors, concrete screed floor and benefits from both power and lighting. The garage also incorporates a mezzanine level for storage purposes. Several outbuildings are contained within the grounds. These consist of a lean-to timber storage shed attached to the garage. A further outhouse is contained within the grounds. This is constructed of brick materials with a pitched roof, felt clad externally, which has recently been fully overhauled and incorporates additional roof supports internally. An external permanent greenhouse is contained within the grounds within the grounds, and this is fitted between the walled garden and is in timber materials under a mono-pitched polycarbonate roof covering. This greenhouse area incorporates its own LPG heating system.
	Visually inspected.
Outside areas and boundaries	Garden grounds are well laid out and we understand, extend to over one acre. These incorporate a walled garden/orchard and are laid out in grass, pave, chip and shrub materials.
	A further garden area is situated to the front of the property, with boundaries being in walls/hedges, and laid out in chip and paved materials. This area also incorporates a log shelter.
	Visually inspected.
Ceilings	Ceilings are in plaster/lath and plasterboard materials, which incorporate some attractive original cornicing and coving in areas throughout.
	Visually inspected from floor level.
Internal walls	Internal walls are of brick/plaster/plasterboard and lath materials in areas throughout. We understand that wall sections are dry-lined internally, and Kingspan has been laid behind plaster work.
	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.

Floors including sub floors	Internal flooring is of solid concrete and suspended timber construction overlaid with floorboards. Floors are covered in a variety of modern and quality hardwood materials.
	Underfloor heating has been fitted to flooring in areas on the ground and the first floor levels.
	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
	Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point.
	Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.
Internal joinery and kitchen fittings	Modern wall/base kitchen units are provided, which incorporate granite work surfaces, integrated appliances and electric induction hob/oven.
	Internal joinery is in quality hardwood and softwood materials.
	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.
Chimney breasts and fireplaces	Original fireplaces are incorporated within the property, and a wood burning stove is fitted within the dining room. In addition, a multi-fuel burner is situated within the main living room. These are flued externally.
	Further original chimneys are assumed to have been blocked, capped and ventilated.
	Visually inspected. No testing of the flues or fittings was carried out.
Internal decorations	Decorated areas include walls, ceilings and internal joinery.
	Visually inspected.
Cellars	Not applicable.

	1
Electricity	The property has a mains supply with PVC coated cabling and consumer unit.
	Thirteen amp power sockets are situated within all main apartments and hallways.
	We understand that the property has been fully re-wired.
	Solar panels are installed, and we understand that these feed into the electrical supply.
	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances.
	Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the Surveyor will state that in the report and will not turn them on.
Gas	There is a mains gas supply to the property.
	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances.
	Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the Surveyor will state that in the report and will not turn them on.
Water, plumbing and bathroom fittings	Modern white sanitary fittings are provided within all main bathrooms, WCs etc.
	Where visible, plumbing installations comprise copper/metal and PVC materials in areas throughout.
	An original well is in evidence to the rear of the property, and we understand that this area has been fully contained and strengthened, as part and parcel of the refurbishment programme. This is currently covered in toughened glass.
	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
	Concealed areas around baths and shower trays cannot be inspected however water spillage over a period of time can result in unexpected defects to hidden parts of the building fabric.

u	
Heating and hot water	A gas fired central heating system is provided within the property. Currently, two boilers are in operation within the subjects. The Worcester floor mounted is functional for the means of the central heating radiators and also hot water within the property.
	A further wall mounted Worcester Greenstar boiler is situated within the utility room, which is for the purpose of underfloor heating within the property.
	Underfloor heating is operational within the ground and first floor.
	Hot water panel radiators are also in operation within some apartments and primarily, on the attic floor.
	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.
	No tests whatsoever were carried out to the system or appliances.
Drainage	Drainage is connected to the Local Authority sewer.
	Drainage covers etc were not lifted.
	Neither drains nor drainage systems were tested.
Fire, smoke and burglar	Smoke detectors are provided.
alarms	An intruder alarm is provided.
	Visually inspected.
	No test whatsoever were carried out to any systems or appliances.
	There is now a requirement in place for compliant interlinked fire, smoke and heat detectors in residential properties. The new fire smoke and alarm standard came into force in Scotland in February 2022, requiring a smoke alarm to be installed in the room most frequently used for living purposes and in every circulation space on each floor. A heat alarm also requires to be installed in each kitchen. The alarms need to be ceiling mounted and interlinked. Where there is a carbon fuelled appliance such as a boiler, open fire or wood burner etc. a carbon monoxide detector is also required. The surveyor will only comment on the presence of a smoke
	detector etc. but will not test them, ascertain if they are in working order, interlinked and / or fully compliant with the fire and smoke alarm standard that was introduced in 2022.
	We have for the purposes of t

Any additional limits to	No access to roof void areas.
inspection	No access to sub-floor areas.
	Fitted floor coverings and large amounts of furniture in areas throughout.
	An inspection for Japanese Knotweed was not carried out. This is a plant which is subject to control regulation, is considered to be invasive and one which can render a property unsuitable for some mortgage lenders. It is therefore assumed that there is no Japanese Knotweed within the boundaries of the property or its neighbouring property. Identification of Japanese Knotweed is best undertaken by a specialist contractor. If it exists removal must be undertaken in a controlled manner by specialist contractors. This can prove to be expensive.
	Normal maintenance is not treated as a repair for the purposes of the Single Survey. When a category 1 rating is provided this means
	the property must continue to be maintained in the normal way.

Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

Coping stone 2 3 Chimney head 4 Flashing 5 **Ridge ventilation** 6 Ridge board (7) Slates / tiles 8 Valley guttering 9 Dormer projection **Dormer flashing Dormer cheeks** 12 Sarking (13) Roof felt (14) Trusses (15) Collar 16 Insulation 17 Parapet gutter (18) Eaves guttering (19) Rainwater downpipe (20) Verge boards / skews (21) Soffit boards 22 Partiton wall 23 Lath / plaster (24) Chimney breast (25) Window pointing (26) Window sills (27) Rendering (28) Brickwork / pointing (29) Bay window projection 30 Lintels (31) Cavity walls / wall ties 32 Subfloor ventilator 33 Damp proof course (34) Base course **35** Foundations (36) Solum

Chimney pots

- (37) Floor joists
- 38 Floorboards
- (39) Water tank
- (40) Hot water tank

2. CONDITION

This section identifies problems and tells you about the urgency of any repairs by using one of the above 3 categories:

Category 3	Category 2	Category 1
	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movement	
Repair category:	
Notes:	We did not detect any evidence of structural movement at the time of our inspection.

Dampness, rot and infestation	
Repair category:	
Notes:	Using a hand held Protimeter, we took sporadic readings in areas and no readings of significance were detected.
	There is evidence to suggest that some damp proofing work appears to have been carried out and as such, any valid Guarantees etc should be transferred to the purchaser.

Chimney stacks	
Repair category:	
Notes:	Original chimneys appear to have been blocked, capped and ventilated. Chimney stacks were found to be in a condition consistent with age and type of property.

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Roofing including roof space	
Repair category:	
Notes:	Roof coverings were fully renewed/replaced approximately 10 years ago. The condition of these should be checked/monitored on a regular/ongoing basis by a reputable Roofing Contractor.
	As mentioned, we were unable gain access to any parts of the roof void area at the time of our inspection.

Rainwater fittings	
Repair category:	
Notes:	Gutters/downpipes have recently been fully overhauled as part and parcel of the refurbishment programme. Ongoing maintenance can be anticipated to these areas.

Main walls	
Repair category:	
Notes:	Walls were found to be in a condition consistent with age and we understand that a programme of re-pointing work has latterly been carried out. Ongoing maintenance can be anticipated to the main walls as part and parcel of any future/ongoing maintenance programme.

Windows, external doors and joinery	
Repair category:	
Notes:	Windows and doors have been replaced in traditional sash and case timber double glazed materials. Again, these were found to be in a condition consistent with age, and general/ongoing maintenance can be anticipated to latches, locks, seals, handles etc.

Category 3	Category 2	Category 1
	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

External decorations	
Repair category:	
Notes:	External decorations were to a satisfactory standard, and have recently been attended to.

Conservatories / porches	
Repair category:	
Notes:	Not applicable.

Communal areas	
Repair category:	
Notes:	Not applicable.

Garages and permanent outbuildings	
Repair category:	
Notes:	The garage was found to be in a condition consistent with age.
	General/ongoing maintenance can be anticipated to these areas as part and parcel of any future/ongoing maintenance programme.

Outside areas and boundaries	
Repair category:	
Notes:	Garden grounds were tidily kept.
	Boundary walls etc were found to be in a condition consistent with age, albeit general/ongoing maintenance can be anticipated to these areas as part and parcel of any future/ongoing maintenance programme.

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Ceilings	
Repair category:	
Notes:	Ceilings were found to be in a condition consistent with age, and re- plastering work appears to have been undertaken during the refurbishment programme.

Internal walls	
Repair category:	
Notes:	Walls were found to be in a condition consistent with age, and wall surfaces were freshly decorated.

Floors including sub-floors	
Repair category:	
Notes:	Floors were found to be in a condition consistent with age. Floor coverings are of a modern style/type throughout, and in modern materials.

Internal joinery and kitchen fittings	
Repair category:	
Notes:	The kitchen fittings are of a modern style/type which appeared functional. Internal joinery was found to be in a condition of good repair, consistent with age.

Chimney breasts and fireplaces	
Repair category:	
Notes:	The wood burner and multi-fuel burner are understood to be functional. It is important to ensure that flues are checked/monitored regularly.
	Further original fireplaces are assumed to have been fully capped/ventilated.

Category 3	Category 2	Category 1
to other parts of the property or cause a safety	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Internal decorations	
Repair category:	
Notes:	The property is in good and fresh decorative order throughout.

Cellars	
Repair category:	
Notes:	Not applicable.

Electricity	
Repair category:	
Notes:	The electrical system appeared functional, and incorporates a trip switch style consumer unit. Current test certification should be exhibited.
	Solar panels are installed and no tests on these were carried out. Your solicitor should confirm the position in relation to these.

Gas	
Repair category:	
Notes:	No major defects were apparent. Current test certification should be exhibited.

Water, plumbing and bathroom fittings					
Repair category:					
Notes:	Sanitary fittings are of a modern style/type which appeared functional.				
	We did not detect any evidence of defect to plumbing installations at the time of our inspection. These areas were however, mainly concealed.				
	An original well is in evidence to the rear of the property, and we understand that this area has been fully contained and strengthened, as part and parcel of the refurbishment programme. This is currently covered in toughened glass. At the time of our inspection, there was no evidence to suggest any defect to this area.				

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Heating and hot water				
Repair category:				
Notes:	The central heating systems are of a modern make/condensing style. Current test certification etc should be exhibited.			

Drainage	
Repair category:	
Notes:	No surface evidence of defect was apparent.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the comments above for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	1
Roofing including roof space	1
Rainwater fittings	1
Main walls	1
Windows, external doors and joinery	1
External decorations	1
Conservatories / porches	
Communal areas	
Garages and permanent outbuildings	1
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	1
Internal decorations	1
Cellars	
Electricity	1
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. ACCESSIBILITY INFORMATION

Guidance Notes on Accessibility Information

Three steps or fewer to a main entrance door of the property: In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres: For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coinoperated machines.

1. Which floor(s) is the living accommodation on?	Ground, First and Attic.
2. Are there three steps or fewer to a main entrance door of the property?	[x]YES []NO
3. Is there a lift to the main entrance door of the property?	[]YES [x]NO
4. Are all door openings greater than 750mm?	[]YES [x]NO
5. Is there a toilet on the same level as the living room and kitchen?	[x]YES []NO
6. Is there a toilet on the same level as a bedroom?	[x]YES []NO
7. Are all rooms on the same level with no internal steps or stairs?	[]YES [x]NO
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	[x]YES []NO

4. VALUATION AND CONVEYANCER ISSUES

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated re-instatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

Absolute ownership assumed.

We are unaware of any adverse planning proposals affecting the property.

Boundaries/rights of way should be checked in the normal manner.

The legal position in relation to solar panels should be ascertained.

Where items of maintenance or repair have been identified, the purchaser should satisfy themselves as to the costs and implications of these issues prior to making an offer to purchase.

Estimated re-instatement cost (£) for insurance purposes

1,000,000

One Million Pounds

Valuation (£) and market comments

625,000

Six Hundred and Twenty Five Thousand Pounds

Report author:	Peter Bennet, MRICS		
Company name:	Dunfermline - Allied Surveyors Scotland Ltd		
Address:	18a Dickson Street Dunfermline KY12 7SL		
Signed:	Electronically Signed: 269134-E2420F9C-7DC3		
Date of report:	20/09/2024		

PART 2.

MORTGAGE VALUATION **REPORT**

Includes a market valuation of the property.





Mortgage Valuation Report

			-		
Property: Milton House		Client: Mr. Ha	Client: Mr. Harry Aitchison		
	54 Main Street Milton of Balgonie, Glenrothes KY7 6PX		ght Ownership		
Date of Inspection:	20/09/2024	Reference:	DD1277		

This report has been prepared as part of the seller's instructions to carry out a Single Survey on the property referred to above. The purpose of this report is to summarise the Single Survey for the purpose of advising a potential lender on the suitability of the property for mortgage purposes. The decision as to whether mortgage finance will be provided is entirely a matter for the lender. You should not rely on this report in making your decision to purchase but consider all the documents provided in the Home Report. Your attention is drawn to the additional comments elsewhere within the report which set out the extent and limitations of the service provided. This report should be read in conjunction with the Single Survey Terms and Conditions (with MVR). In accordance with RICS Valuation – Global Standards 2017 this report is for the use of the party to whom it is addressed or their named client or their nominated lender. No responsibility is accepted to any third party for the whole or any part of the reports contents. Neither the whole or any part of this report may be included in any document, circular or statement without prior approval in writing from the surveyor.

1.0 LOCATION

The subjects are situated close to the centre of the village of Milton of Balgonie within an established residential location, where surrounding properties are of a residential nature. All normal local amenities and facilities are available locally and within the nearby town of Glenrothes, which lies approximately 2 miles to the West.

2.0	DESCRIPTION	2.1 Age:	1795 (approx). The		
			subjects were substantially		
			extended to the rear circa		
			10 years ago.		

The subjects comprise a large Georgian detached villa with rear/side extensions.

3.0 CONSTRUCTION

Traditional solid stone construction under a pitched roof, slate clad externally.

4.0 ACCOMMODATION

GROUND FLOOR:

Entrance Vestibule/Hall, Living Room, Dining Room, Large Open Plan Orangery/further Living Space to the rear, Dining Kitchen, Shower Room and Utility Room.

FIRST FLOOR:

Landing, Further Living Room, Two Bedrooms and Shower Room.

ATTIC FLOOR:

Two further Bedrooms and Bathroom.

5.0	SERVICES (No tests have been applied to any of the services)							
Water:	Mains	Mains Electricity: Mains Gas: Mains Drainage: Mains						
Central Heat	Central Heating: Full gas fired central heating system installed.							
6.0	OUTBUILDINGS							

Milton House, 54 Main Street, Milton of Balgonie, Glenrothes, KY7 6PX

Garage:		Double.				
Others:		Several outbu	buildings/large greenhouse.			
 GENERAL CONDITION - A building survey has not been carried out, nor has any inspection been made of any woodwork, services or other parts of the property which were covered, unexposed or inaccessible. The report cannot therefore confirm that such parts of the property are free from defect. Failure to rectify defects, particularly involving water penetration may result in further and more serious defects arising. Where defects exist and where remedial work is necessary, prospective purchasers are advised to seek accurate estimates and costings from appropriate Contractors or Specialists before proceeding with the purchase. Generally we will not test or report on boundary walls, fences, outbuildings, radon gas or site contamination. The subjects were found to be in a condition of good repair, consistent with age. General/ongoing maintenance work can be anticipated to areas externally. 						
-				r, with modern fixtures and fit he last 10-15 years.	tings througho	out. The house
8.0		_		on of any mortgage or, to pre	eserve the con	dition of the
None.						
8.1 Retention	n recommende	ed:	-			
9.0	ROADS & FO	OTPATHS				
Made.						
10.0	BUILDINGS I (£):	NSURANCE	1.000.000	GROSS EXTERNAL FLOOR AREA	315	Square metres
	This figure is an opinion of an appropriate sum for which the property and substantial outbuildings should be insured against total destruction on a re-instatement basis assuming reconstruction of the property in its existing design and materials. Furnishings and fittings have not been included. No allowance has been included for inflation during the insurance period or during re-construction and no allowance has been made for VAT, other than on professional fees. Further discussions with your insurers is advised.					
11.0	GENERAL R	EMARKS				
We are unaw Boundaries/ri Where items costs and imp	ghts of way sho of maintenance plications of the	erse planning p ould be checke e or repair have se issues prior	ed in the norma e been identifie r to making an	ed, the purchaser should satis offer to purchase.	-	
12.0	VALUATION On the assumption of vacant possession and that the property is unaffected by any adverse planning proposals, onerous burdens, title restrictions or servitude rights. It is assumed that all necessary Local Authority consents, which may have been required, have been sought and obtained. No investigation of any contamination on, under or within the property has been made as we consider such matters to be outwith the scope of this report. All property built prior to the year 2000 may contain asbestos in one or more of its components or fittings. It is impossible to identify without a test. It is beyond the scope of this inspection to test for asbestos and future occupants should be advised that if they have any concerns then they should ask for a specialist to undertake appropriate tests.					
12.1	Market Value in present condition (£):625,000Six Hundred and Twenty Five Thousand Pounds				ounds	
12.2	Market Value completion o works (£):					
12.3	Suitable secu normal morto purposes?	-	Yes			
12.4	Date of Valua	ition:	20/09/2024			

Signature: Electronically		Signed: 269134-E2420F9C-7DC3				
Surveyor:	Peter Bennet		MRICS		Date:	20/09/2024
Dunfermline - Allied Surveyors Scotland Ltd						
Office:	18a Dickson StreetTel: 01383 728 833DunfermlineFax:KY12 7SLemail: dunfermline@alliedsurveyorsscotland.com		otland.com			



ENERGY **Report**

A report on the energy efficiency of the property.



energy report

energy report on:

Milton House
54 Main Street
Milton of Balgonie, Glenrothes
KY7 6PX

Customer	Mr. Harry Aitchison
----------	---------------------

Customer address	Milton House
	54 Main Street
	Milton of Balgonie, Glenrothes
	КҮ7 6РХ

Prepared by	Peter Bennet, MRICS
	Dunfermline - Allied Surveyors Scotland Ltd

Energy Performance Certificate (EPC)

Scotland

Dwellings

MILTON HOUSE, 54 MAIN STREET, MILTON OF BALGONIE, GLENROTHES, KY7 6PX

Dwelling type:DeDate of assessment:23Date of certificate:10Total floor area:28Primary Energy Indicator:96


Detached house 23 September 2024 10 October 2024 281 m² 96 kWh/m²/year Reference number: Type of assessment: Approved Organisation: Main heating and fuel: 0100-2457-7110-2624-2645 RdSAP, existing dwelling Elmhurst Boiler and radiators, mains gas


You can use this document to:

· Compare current ratings of properties to see which are more energy efficient and environmentally friendly

Estimated energy costs for your home for 3 years*

^t based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions





Energy Efficiency Rating

£6,717

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band B (88)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band B (86)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

There are currently no improvement measures recommended for your home.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282. THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

MILTON HOUSE, 54 MAIN STREET, MILTON OF BALGONIE, GLENROTHES, KY7 6PX 10 October 2024 RRN: 0100-2457-7110-2624-2645 **Recommendations Report**

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Granite or whinstone, with internal insulation	****	*****
Roof	Pitched, 300 mm loft insulation	****	*****
Floor	Suspended, insulated	—	
Windows	Fully double glazed	****	★★★★☆
Main heating	Boiler and radiators, mains gas	★★★ ☆	★★★★ ☆
Main heating controls	Programmer, room thermostat and TRVs	★★★ ☆	★★★★ ☆
Secondary heating	Room heaters, wood logs	_	
Hot water	From main system, plus solar	****	****
Lighting	Low energy lighting in all fixed outlets	****	*****

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 15 kg $CO_2/m^2/yr$.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 4.2 tonnes of carbon dioxide every year. You could reduce emissions by switching to renewable energy sources.

MILTON HOUSE, 54 MAIN STREET, MILTON OF BALGONIE, GLENROTHES, KY7 6PX 10 October 2024 RRN: 0100-2457-7110-2624-2645 **Recommendations Report**

Estimated energy costs for this home					
	Current energy costs	Potential energy costs	Potential future savings		
Heating	£5,691 over 3 years	£5,691 over 3 years			
Hot water	£384 over 3 years	£384 over 3 years	Not an all and the		
Lighting	£642 over 3 years	£642 over 3 years	Not applicable		
Totals	£6,717	£6,717			

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

None

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present:

- Biomass secondary heating
- Solar water heating
- Solar photovoltaics

Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation	
Space heating (kWh per year)	23,151	N/A	N/A	N/A	
Water heating (kWh per year)	2,388				

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Assessor membership number: Company name/trading name: Address:	Mr. Peter Bennet EES/014875 Allied Surveyors Scotland Ltd 18a Dickson Street Dunfermline KY12 7SL
Phone number:	01383 738 585
Email address:	dunfermline@alliedsurveyorsscotland.com
Related party disclosure:	No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

PART 4.

PROPERTY QUESTIONNAIRE

The owner of the property is required to complete this document which asks for information on the property such as 'Which council tax band?' etc.



•

Property Address: MILLON HOUSE 54 MOUNST MULLON of Balgonie FIFE KY76PX.

Seller/s:

· * 1

Harry Altchiron

Completion date of Property Questionnaire:

17, 9, 2024

. .

Note for sellers

• ••••

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

Information to be given to prospective buyer(s)

1	Length of ownership	· · · · · · · · · · · · · · · · · · ·		
	How long have you owned the property?	14 4	ris	
2	Council Tax	· · · · · · · · · · · · · · · · · · ·		
	Which Council tax band is your property in?	F		
3	Parking (tick all applicable)			
	Garage			-
	Allocated Parking Space			
	Shared Parking			
	On Street			
	Metered Parking			
	Other (Please specify)			
	ON PrivATE ROAD.			
		× • • • • • • • • •		
4	Conservation area		Yes	
	Is your property in a designated Conservation area (that		No	
	is an area of special architectural or historical interest, the character or appearance of which it is desirable to		Unknown	-
	preserve or enhance)?			

. . .

5	Listed buildings		
		Yes	
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special	No	- <u> </u>
	architectural or historical interest)?	Unknown	
6	Alterations/additions/extensions	<u></u>	
a (i)	During your time in the property, have you carried out any structural alterations, additions or extensions (for example,	Yes	
	provision of an extra bath/shower room, toilet or bedroom)?	No	÷
	If you have answered Yes, please describe below the changes which you have made:	Unknown	-
	Which you have made: ERECT ORANDGERY TO REAR OF BULLION WEND KITCHEN ENTEND GARAGE.		· .
	New KITCHEN ENTEND GARAGE.		
(ii)	Did you obtain planning permission, building warrant, completion	Yes	
	certificate and other consents for this work?	No	1
		Unknown	
	If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.		
	If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:		
b	Have you had replacement windows, doors, patio doors or double glazing installed in your property?	Yes	~
		No	
	If you have answered Yes, please answer the 3 questions below:	Unknown	
(i)	Were the replacements the same shape and type as the ones you replaced?	Yes	~
		No	
		Unknown	
(ii)	Did this work involve any changes to the window or door openings?	Yes	
		No	\checkmark
		Unknown	
(iii)	Please describe the changes made to the windows, doors, or patio doors (with approximate dates when the work was completed):		
	Please give any guarantees which you received for this work to your solicitor or estate agent.		

7	Central heating		
a	Is there a central heating system in your property?	Yes	1/
		No	~
	(Note: a partial central heating system is one which does not heat	Partial	
	all the main rooms of the property – the main living room, the bedroom/s, the hall and the bathroom)		
		Unknown	
	If you have answered Yes or Partial – what kind of central heating is there?	7. 4	
	(Examples: gas-fired, solid fuel, electric storage heating, gas, warm air).		
	If you have answered Yes, please answer the 3 questions below:		
(i)	When was your central heating system or partial central heating system	stem installed?	,
	10 YRS		
(ii)	Do you have a maintenance contract for the central heating	Yes	V
	system?	No	
	If yes, please give details of the company with which you have a	Unknown	
	maintenance contract:	WORCEST	EK
		WORCEST BOSCA	+ ·
			`
(iii)	When was your maintenance agreement last renewed? (please provyear) $08/12/2023$	vide the month	and
8	Energy Performance Certificate		
	Does your property have an Energy Performance Certificate which is less than 10 years old? (PLEASE NOTE: Please tick ' YES ' as the surveyor will complete this at the time of inspection)	Yes	~
		<u> </u>	·
9	Issues that may have affected your property	.	
а	Has there been any storm, flood, fire or other structural damage	Yes	
	to your property while you have owned it?	No	
		Unknown	
	Thus, have answered Versia the demans the subject of any	Yes	
	If you have answered Yes, is the damage the subject of any outstanding insurance claim?	No	
		NO	
Ь	Are you aware of the existence of asbestos in your property?	Yes	
	The you aware of the existence of aspestos in your property?	No	
	If you have answered Yes, please give details:	Unknown	
			·

······································				
Please tick which services	s are connecte	d to your property and give deta	ils of the supp	lier
ices	Connected	Supplier	•••••••••••••••••••••••••••••••••••••••	
or liquid petroleum gas	GAS	SCOTTIS# GAS		
er mains or private water ly	mainos	SCOTTISH WATER.		
ricity	YES	1111 ELECTRICT	⊽५ ∙	
s drainage	YES			
phone	YES.	SKY		
e TV or satellite	Solutive	SKY		
dband	YES	SKY .		
Is there a septic tank sys	stem at your p	roperty?	Yes	Γ
n n terraren erraren er		n an	No	
			Unknown	
				<u> </u>
If you have answered Ve		or the 2 questions below		
	the second day of the second d		Yes	T
tank?			No	
			Unknown	
Do you have a maintena	nce contract fo	r your septic tank?	Yes	+
•		· ·	No	
	or liquid petroleum gas er mains or private water ly ricity s drainage ohone e TV or satellite dband Is there a septic tank sys <u>If you have answered Ye</u> Do you have a maintenan If you have a maintenan	or liquid petroleum gas GAS er mains or private water wwwws ly Wwws ricity YES s drainage YES ohone YES ohone YES e TV or satellite Societtife dband YES Is there a septic tank system at your private answered Yes, please give If you have answered Yes, please give	or liquid petroleum gas QAS Scottisk GAS er mains or private water MOUNDS Scottisk WATEL ricity YES 1.1.1 ELECTRICT s drainage YES SKY ohone YES SKY e TV or satellite Sottellite SKY dband YES SKY Is there a septic tank system at your property? If you have answered Yes, please answer the 2 questions below: Do you have appropriate consents for the discharge from your septic	or liquid petroleum gas GAS Scottisk GAS ir mains or private water MOUOS Scottisk WATEA ir mains or private water MOUOS Scottisk WATEA irricity YES 1 · · · / Electricity is drainage YES 1 · · · / Electricity obnone YES SKY e TV or satellite SOTELITE SKY dband YES SKY Is there a septic tank system at your property? Yes No Unknown If you have answered Yes, please answer the 2 questions below: No Do you have appropriate consents for the discharge from your septic tank? Yes No Unknown Do you have a maintenance contract for your septic tank? Yes If you have answered Yes, please give details of the company with No

11	Responsibilities for shared or common areas		
а	Are you aware of any responsibility to contribute to the cost of	Yes	
	anything used jointly, such as the repair of a shared drive,	No	V
	private road, boundary, or garden area?	Unknown	
	If you have answered Yes, please give details:		
b	Is there a responsibility to contribute to repair and maintenance	Yes	
	of the roof, common stairwell or other common areas?	No	
		Unknown	
	If you have answered yes, please give details:	N/A	
с	Has there been any major repair or replacement to any part of	Yes	
	the roof during the time you have owned the property?	No	レ
		Unknown	
d	Do you have the right to walk over any of your neighbours'	Yes	
-	property – for example to put out your rubbish bin or maintain	No	
	your boundaries?	Unknown	
	If you have answered Yes, please give details:		÷
e	As far as you are aware, do any of your neighbours have the	Yes	
	right to walk over your property, for example to put out their	No	
	rubbish bin or to maintain their boundaries?	Unknown	
	If you have answered Yes, please give details:		
f	As far as you are aware, is there a public right of way across any	Yes	1
	part of your property? (public right of way is a way over which	No	+./
	the public has a right to pass, whether or not the land is privately	Unknown	
	owned.)		<u>l</u>
	If you have answered Yes, please give details:		
12	Charges associated with your property		
а	Is there a factor or property manager for your property?	Yes	
		No	V
	If you have answered Yes, please provide the name and address, and give details of any deposit held and approximate charges:	Unknown	

			-
b	Is there a common buildings insurance policy?	Yes	
		No	
		Unknown	
	If you have answered Yes, is the cost of the insurance included in		
	your monthly/annual factor's charges?	Yes	
		No	
		Unknown	1
с	Please give details of any other charges you have to pay on a regul		<u> </u>
3	upkeep of common areas or repair works, for example to a residen maintenance or stair fund.	ts' association, o	
			,
13	Specialist works		;
а	As far as you are aware, has treatment of dry rot, wet rot, damp	Yes	
	or any other specialist work ever been carried out to your	No	
	property?	Unknown	
	If you have answered Yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property: BEFORE BONGWE the property		
b	As far as you are aware, has any preventative work for dry rot,	Yes	
1	wet rot or damp ever been carried out to your property?	No	~
		Unknown	
	If you have answered Yes, please give details:		
С	If you have answered Yes to 13(a) or 13(b), do you have any	Yes	
	guarantees relating to this work?	No	
		Unknown	
	If you have answered Yes, these guarantees will be needed by		
	the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself, <u>please</u> <u>write below who has these documents</u> and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate.	potensi e se statoj se se se te se se se	: . •
	Guarantees are held by:		

14	Gu	arantees				· · · · · · · · · · · · · · · · · · ·	
a		e there any guarantees or warranties for a	ny of	the fo	llowing?		
			No	Yes	Don't know	With title deeds	Lost
i)		Electrical Work	\checkmark				
ii)		Roofing	\checkmark				
iii)		Central Heating	\checkmark				
iv)		National House Building Council (NHBC)	~				
v)		Damp course	/				
vi)		Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)	~				
		rou have answered 'Yes' or 'with title deec tallations to which the guarantee(s) relate		-			
с		there any outstanding claims under any	of the	guara	ntees	Yes	
	list	ed above?				No Unknown	V
	If y	ou have answered Yes, please give detail	s:				
15		undaries					
		far as you are aware, has any boundary over the last 10 years?	of you	r prop	erty been	Yes No	
						Unknown	•
	If y	ou have answered Yes, please give detail	s?				

16	Notices that affect your property		
In th	e past 3 years have you ever received notice:		
		Yes	
а	Advising that the owner of a neighbouring property has made a	No	
	planning application?	Unknown	
b	That affects your property in some other way?	Yes	<u> </u>
		No	
		Unknown	
	That requires you to do any maintenance, repairs or improvements to your property?	Yes	
с		No	V
		Unknown	-
agent	I have answered Yes to any of a-c above, please give the notices to , including any notices which arrive at any time before the date of e ur property.		

Declaration by the seller(s)/or other authorised body or person(s)

I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature(s):

• • • •

1

Date: 17, 9, 2024